DHP-W306AV A1 Firmware Release Notes

Firmware: FW1.01

Hardware: A1

Date: 2010/09/13

Problems Resolved:

1. Improved performance

2. Fixed unable to save a Qos mac address without splinter(:) on the PLC Settings page

3. Added the status of Wi-Fi Protected Setup on the Device Info page

Enhancements:

1. Supported Win7 Logo

2. Supported D-Link SOHO AP Setup Wizard Specification v1.02

Known Issues:

None