

**Firmware Version:** V2.00_4017**Prom Code Version:****Published Date:** 2014/6/17**Content:**

Upgrading Instructions:	2
New Features:	2
Problems Fixed:	2
Known Issues:	2
Related Documentation:	2

Revision History and System Requirement:

Firmware Version	Date	Model	Hardware Version
V2.00_4017	2014/6/17	DCS-942L	B1

Upgrading Instructions:

Follow the steps below to upgrade the firmware:

1. Download the latest firmware file from the D-Link website. The file is in .bin file format.
2. Log-in camera web UI and enter setup/Maintenance/Firmware upgrade
3. Click Browse... and specify the firmware file.
3. Click Upgrade. The camera starts to upgrade and will reboot automatically when the upgrade completes.

New Features:

Fireware Version	New Features
V2.00_4017	<ol style="list-style-type: none">1. The 1st FW version for DCS-942L rev.B1. FW cannot backward compatible with Ax FW2. mydlink agent v2.0.17-b613. Add sensitivity settings for light sensor on device Web GUI

Problems Fixed:

Firmware Version	Problems Fixed
V2.00_4017	<ol style="list-style-type: none">1. Fixed the issue that adhoc connection cannot be established after configuration.

Known Issues:

Firmware Version	Known Issues

Related Documentation:

N/A