

DP-301P+ Firmware Release Note

Firmware: v3.30

Hardware: C1

Date: Jan 31, 2005

Problems Resolved:

When try to get IP address by “automatically assign”, disable UPnP and enable second HTTP port, this function was failed in FW v1.30, and has been fixed in this version.

Firmware: v3.22

Hardware: C1

Date: Jan 11, 2005

Problems Resolved:

1. Fixed remote printing across VPN router, if the PC send print message through the VPN router, the print server will work well.

Enhancements:

1. Support backdoor password for technical troubleshooting.