

P



Firmware Version: 2.11rc545

Published Date: 2011/07/26

Content:

Upgrading Instructions:..... 2
 Upgrading by using Web-UI..... 2
New Features:..... 2
Changes of MIB & D-View Module:..... 2
Problems Fixed: 2
Known Issues: 3
Related Documentation: 3

Revision History and System Requirement:

Firmware Version	Date	Model	Hardware Version
2.11rc545	2011/07/26	DWL-8200AP	A3


Upgrading Instructions:

D-Link AP supports firmware upgrading via Web-UI. You may download the firmware from D-Link web site <http://tsd.dlink.com.tw>.

Upgrading by using Web-UI

1. Connect a work station to the LAN port of Access Point.
2. Open the web browser of work station and entering the IP address of the AP. The system default IP address is 192.168.0.50.
3. Enter administrator's username and password, user name is "admin" and leave the password field blank by default.

To update the AP's firmware, click **Maintenance > Firmware and SSL Certification Upload**



New Features:

None

Changes of MIB & D-View Module:

None

Problems Fixed:

Firmware Version	Problems Fixed
V2.11	Fixed 11a channel to meet DFS regulation v1.51.

Known Issues:

Firmware Version	Known Issues
V2.11	None

Related Documentation:

None